- Place template on mounting surface, aligning mounting holes with structural features (mounting surface or stud)
- Ensure access port "A" is aligned with wiring source
- Mark location that fasteners will attach to using the centerline marks provided
- Remove template from mounting surface
- Run network cable through bracket arm as needed, then fasten bracket arm to mounting surface at previously marked locations using hardware appropriate to the facility building materials

⌀ .512 in.
2 PLACES

2.000 in.

4.000 in.

5.500 in.

5.500 in.

ACCESS PORT "A"